

Issued by External campaigns, Volvo Trucks
2023-12-20

S3757

Silencer, DPF sensor, replace. FH/FM (4)

Markets concerned

VTC, Sweden, Norway, Denmark, Finland, Iceland, Belgium, Great Britain, France, Greece, Netherlands, Italy, Portugal, Switzerland, Spain, Germany, Austria, Slovenia, Bosnia, Croatia, Macedonia, Serbia, Montenegro, Bulgaria, Hungary, Ukraine, Latvia, Lithuania, Estonia, Kazakhstan, Armenia, Czech Republic, Georgia, Slovakia, Poland, Romania, Moldova, Albania, Palestine, Iran, Israel, Japan, Jordan, Turkey, India, Korea, Taiwan, United Arab Emirates, China, Hong Kong, Singapore, Morocco, Cyprus, Australia, New Zealand.

Concerns

24-HDV, TYPE-FH/FM, EM-EU6, ENG-VE11/ENG-VE13, OBDEP-D/OBDEP-E, TURBO-S

Brief Description

The DPF differential pressure sensor malfunction might potentially cause either filter clogging or constant regeneration trigger, which in consequence affects the fuel consumption.

To be carried out

Volvo Trucks requires that all vehicles concerned shall be rectified before delivery to the customer or, at the next service occasion but within the stipulated time period.

Vehicles concerned

To be found in VDA+.

Material

See next page.

Note: All material can be requested back to the Warranty Material Department and are therefore to be treated according to the existing rules (see Warranty Binder 16.1–16.5).

Compensation

Main op: 28513. Differential pressure sensor, replace. (M)

Max. labour: According to Impact.

Debit code: 13

Defect code: 09

Causal part number: 23488881

Closing date: See Campaign Info.

Material

Note: Stock orders class to be used for all orders (order class 3).

Part number	Description	Max. qty.	M/O	Notes
24405156	Sensor	1	Mandatory	
994501	Flange screw	4	Mandatory	
21229589	Hose	1	Optional	
21321338	Clamp	2	Optional	

Method

1 Replace the DPF sensor. *28513-2 Differential pressure sensor, replace*