

S3757

Issued by External campaigns, Volvo Trucks
 2023-12-05

Silencer, DPF sensor, replace. FH/FM (4)

Description

Replacement of the DPF sensor.

Markets concerned

VTC, Sweden, Norway, Denmark, Finland, Iceland, Belgium, Great Britain, France, Greece, Netherlands, Italy, Portugal, Switzerland, Spain, Germany, Austria, Slovenia, Bosnia, Croatia, Macedonia, Serbia, Montenegro, Bulgaria, Hungary, Ukraine, Latvia, Lithuania, Estonia, Kazakhstan, Armenia, Czech Republic, Georgia, Slovakia, Poland, Romania, Moldova, Albania, Palestine, Iran, Israel, Japan, Jordan, Turkey, India, Korea, Taiwan, United Arab Emirates, China, Hong Kong, Singapore, Morocco, Cyprus, Australia, New Zealand.

Opening date YYMMDD	Closing date YYMMDD	Debit code	Age limit months	PSI
231205	See Campaign Info.	13	0-999	3757
Main operation	Defect code	Max. labour	Max. subcontract	
28513	09	See Compensation.	0 SEK	
Causal part number	Causal part number	Causal part number	Causal part number	
23488881				
Compensation level	Age range	Percent	Max. mileage	
Volvo Trucks commitment	0-999	100	9999999	

Compensation

Main op: 28513. Differential pressure sensor, replace. (M)
Max. labour: According to Impact.