

# Product Service Information SCC Information

Date Group No. Release Page 5.19 **258 0146 02** 1(2)

P0146

Issued by External campaigns, Volvo Trucks 19-05-21

# Urea pump, replace (step C). 2nd repair. FH/FM (4)

## **Description**

Replacement of the urea pump.

With variants: 24-HDV, EM-EU6, OBDEP-C.

**Note:** This Policy can only be used if Guided Diagnostic fault tracing for fault codes leads to that the pump unit must be replaced. Write the DTCs in the claim.

#### **Markets**

VTC, Sweden, Norway, Denmark, Finland, Iceland, Belgium, Great Britain, France, Greece, Netherlands, Italy, Portugal, Switzerland, Spain, Germany, Austria, Slovenia, Bosnia, Croatia, Macedonia, Serbia, Montenegro, Bulgaria, Hungary, Ukraine, Belarus, Latvia, Russia, Lithuania, Estonia, Kazakhstan, Czech Republic, Slovakia, Poland, Romania, Moldova, Albania, Palestine, Israel, Japan, Malaysia, Turkey, Korea, Taiwan, China, Hong Kong, Singapore, Morocco, Australia.

Opening date YYMMDD	Closing date YYMMDD	Debit code	e Age limit m	onths	PSI
1800419	See Campaign Info	13	13-48		No
Operation No: 25807 (M)			Defect code: 09		
Max. labour: See Special information			Max. subcontract: 0 SEK		
Causal p/n Causal p/n		Causal p/n Causal p/n			
22209517	85013391		22341154	2260824	14
85020468	22610216		85020666		
Chassis series	Chassis interval		Chassis series		nassis interval
А, В					
Compensation level	Age range		Percent		ax. mileage
Volvo Trucks commitme	ent 13-48	13-48 10		99	99999

#### Vehicles concerned

Will be found in VDA+ for policy P0146 (under outstanding campaigns per vehicle).

### **Special information:**

Main op: 25807. Pump unit, replace. (M) **Max labour: According to Impact.** 

#### **Material**

Part No	Description	Max qty	M/O	Notes
22924489	Pump unit	1	0	
85021199	Pump unit, exch	1	0	

#### Method

**Note:** Ensure that there are no outstanding software campaigns for the EMS and ACM. If so, they must be performed before using this policy.

**Note:** This Policy can only be used if Guided Diagnostic fault tracing for fault codes leads to that the pump unit must be replaced. Write the DTCs in the claim.

**Note:** If/when the workshop is asked to return the old part, make sure all protection covers are installed on the pump unit.

1 Replace the pump unit. Impact operation 25807-2 Pump unit, replace.